



by Honeywell

Date: September 7th, 2012

Subject: Miller harness D-Ring

With respect to the unauthorized “safety alert” that has been circulating regarding Miller by Honeywell harnesses, Honeywell Safety Products is issuing this notice to ensure our customers that we have conducted a thorough internal investigation to determine root cause.

The left side of Figure 1.1 below shows a Miller Duraflex harness in which the D-ring has been correctly assembled into the harness. The right side of Figure 1.1 shows the same harness with the D-ring incorrectly assembled into the harness.

We have conducted a thorough investigation and determined that the incorrect assembly was a very isolated incident limited to a specific batch of harnesses. We have been in close contact with the customers to whom these harnesses were shipped and have quarantined the (2) incorrect harnesses.




Figure 1.1

We recommend that end-users continue to perform pre-use inspection before donning their harnesses for use to inspect for this condition. We believe we have identified all incorrectly assembled harnesses; however, if you find any such harness, take such harness out of use immediately and let us know.

We apologize for the inconvenience but want to ensure our customers that your safety is our absolute highest priority. We are evaluating our detection methods to prevent products with errors like this from leaving our factory.

Best Regards,

David Vernon
Quality Engineering Manager
Honeywell Safety Products

Honeywell Safety Products
1345 15th Street - P.O. Box 271
Franklin, PA 16323 USA
T: 800-873-5242